

## TAUPIRI COMMUNITY BOARD

Township Inspection: 27 January 1996  
at 8.30 am

**PRESENT:** Mrs E Gouk (Chairperson)  
Miss K Gouk  
Mr W F Hansen  
Mrs K Davies  
Mrs T Tamati  
Mrs G Hansen (Secretary)

**APOLOGY:** Mr T Murphy

Te Putu St/  
Greenlane Road

Shrubs require pruning.

Te Putu St/  
Great South Road

Garden requires weeding.

Bus Shelter - Eastern  
side Great South Road

Eastern side Great South Road - requires repainting.

✓ Pay phone box  
Cnr Te Putu St/Great  
South Road.

- siting to be checked by Transit NZ, although Mrs Chi of Greenstone International has a preference

\* Footpath - Great  
South Road

Between Te Putu St and Lovell Crescent - several holes need repair especially outside number 69.

111 Great South Road

Flax growing and spreading on boundary.

Lovell Crescent

Cul-de-sac: in conjunction with Railway land, long grass hiding rubbish; grass is growing in tarseal - when is resealing due? Seal sun by cess pit.

✓ 83 Great South Road

- Trees outside boundary need sever pruning; woolly nightshade growing and also on reserve land next to 123; reserve land overgrown  
- Need mowing?.

✓ 123 Great South Road

Verge growth from 123 Great South Road south to Community Board boundary - should be mowed back to fences; more woolly nightshade growing in hollow north of metal stockpile area, on east side of road.

\* Great South Road  
- West side

- footpath to be continued to Community Board boundary, verges to be mowed to fences.

110 Great South Road	Barbed wire fences stretching 3-4 properties north of 110 Great South Road.
Cnr Kainui and Great South Rds	Vacant land - contact owner to clear gorse, blackberry etc, to keep tidy.
120 & 124 Great South Road	Front half of no. 124 and most of no. 120. Contact owners to clear and keep land clean.
104 - 124 Great South Road	Grass clippings dumped at base of street light on verge.
Old and new Great South Roads	<ul style="list-style-type: none"> <li>- Ponding problem still exists in wet weather.</li> <li>- Drain at base of bank from new Great South Road to old road to be sprayed and cleaned.</li> <li>- Footpath in same area requires repairing.</li> <li>- Dock creeping along fence line by barrier, old road.</li> </ul>
Great South Road	Footpath: west side up to Welcome Inn. Kerb and channel promised two years ago. Holes in edge of road outside Taupiri Motorcycle Club Inc and adjoining properties.
Privet	All privet in township to be sprayed.
Street Light	South end, property owned by Mrs M Burke. Inspection cover missing at base - light not visible because of overgrown tree.
9.H. Burke property	Waikato District Council to mow grass both sides of footpath - power cables? water mains? Footpath never re-instated. Trees growing over footpath.
Stormwater run-off	Three houses south of Welcome Inn.
Old pumps, wharf	- ex NZCDC. Part of sale from Waikato Frozen Products to Waikato District Council - proposed water supply for Taupiri before Hopu Hopu became available.
Bob Byrne Memorial Park	<ul style="list-style-type: none"> <li>- Boat ramp - upgrade promised by Waikato District Council</li> <li>- Northern entrance - tarseal repairs and extensions</li> <li>- Toilet block</li> <li>- Holes in road edge at turn-off to northern entrance</li> </ul>
Great South Road	Footpath - eastern side of Gordonton Road to Te Putu St - reseal repairs.
Great South Road/ Gordonton Road	<ul style="list-style-type: none"> <li>- Clean roading chips away and paint edges with night visible paint.</li> <li>- North; verges to be mowed from Bob Byrne Park north to Mangawara Bridge and outside Gibson's house - No. 3 Great South Road.</li> </ul>